

STATINTL

JUL 21 1953

Chief, Space, Maintenance and Facilities Division

THRU : Acting Chief, Administrative Staff, Logistics  
Chief, Transportation Division

MFB

STATINTL

facility

STATINTL

1. The "black top" paving on the [redacted] Street side of [redacted] immediately adjacent to the building in the vicinity of the gasoline pump has deteriorated and developed depressions to such an extent that it is difficult to drive vehicles up to the gasoline tank without causing serious damage to them.

2. It is requested that action be taken to have the area repaved to avoid damage to agency passenger cars and trucks.

STATINTL

*Forwarded for appropriate action*  
*7/22/53*

Document No.	001
No Change in Class.	<input checked="" type="checkbox"/>
<input type="checkbox"/> Declared	
Class. Change	TS S C
Auth.	HR 78-2
Date	OCT 19 1953
By	013

2937